Neighbourhood Plan check list

Site SS5 Lower Kirklington Road

	NP	Dismisses flood risk but site was part flooded in 2013. Hopkiln and Maltkiln Cottages suffer from regular surface water flooding. Reference to Potwell dyke is irrelevant as it is on the other side of the town and flood water here comes from Halam Hill and Seems to be a potentially reasonable sw plan but will the combined sewer in LKR by able to cope?	Same comment apply. Paras 4.10 & 4.13 don't ties up with local observations regarding flooding on the site.
		Maltkiln Cottages suffer from regular surface water flooding. Reference to Potwell dyke is irrelevant as it is on the other side of the town and flood water here comes from Halam Hill and Seems to be a potentially reasonable sw plan but will the	
		Maltkiln Cottages suffer from regular surface water flooding. Reference to Potwell dyke is irrelevant as it is on the other side of the town and flood water here comes from Halam Hill and Seems to be a potentially reasonable sw plan but will the	
		Maltkiln Cottages suffer from regular surface water flooding. Reference to Potwell dyke is irrelevant as it is on the other side of the town and flood water here comes from Halam Hill and Seems to be a potentially reasonable sw plan but will the	
		Maltkiln Cottages suffer from regular surface water flooding. Reference to Potwell dyke is irrelevant as it is on the other side of the town and flood water here comes from Halam Hill and Seems to be a potentially reasonable sw plan but will the	
		Maltkiln Cottages suffer from regular surface water flooding. Reference to Potwell dyke is irrelevant as it is on the other side of the town and flood water here comes from Halam Hill and Seems to be a potentially reasonable sw plan but will the	
		Seems to be a potentially reasonable sw plan but will the	
		· · · · · ·	Same comments apply.
		Doesn't conform to NP policy E4 and SS5 vi as PROW runs along estate road.	Now only a very short length on the highway.
		n/a	n/a
		Solar/PV panels would be good to see	Solar/PV panels would be good to see
		OK	ОК
		OK	OK
-		n/a	n/a
-		1,4	1,70
		See F4	See E4
		'	just over 400m to bus stop
		Dismisses extra traffic and says most will walk to the town Centre. However it is way beyond the 800m/10 minute walk isocrone beyond which DfT research shows that most people would walk especially if carrying shopping.	Same comments apply. NB County Highways pushed for traffic lights at the junction rather than a mini roundabout!!
		225 spaces -two per house generally but 1 per house for 1B2P	Police don't like the large parking court
+		n/a	n/a
-			
		n/a	n/2
			n/a
			n/a
		·	n/a
		n/a	n/a
3	30dph	38 dph Doesn't quite conform to DC or NP type %ages although the correct proportion of social housing is very welcome.	Reduced numbers welcome but now doesn't comply with NP %ages for smaller houses. Correct proportion of social housing is very welcome.
6	55	105 – far more than allocated in this unsustainable location which will generate a lot of car journeys with congestion and parking issues in the town centre	80
,		23%	13%
	1+2b=60%	29% 1+2b = 52%	35% 1+2b = 47.5%
			21%
			15% 4b+ = 31.5%
			9%
-b			8%
		nii but reasons seem to some, but not all, to be acceptable.	nil but reasons seem to some, but not all, to be acceptable.
3	30%	OK	ок
	00,00.	ОК	ОК
		Inadequate open space and in the wrong place. NSDC Green Space Improvement plans show a shortfall of Provision in North Ward amounting to 1.29ha for Children and young people and 1.28ha for parks and gardens. It goes on to say "Any significant new housing in the areas may require additional provision considering current deficiency levels."	Now much better provision and location.
n	n/a	Considering current denoteticy levels.	
	• •		
Eiv		Doesn't provide central open space/play area, to give a sense of	Now much better provision and location.
IX		place and focal point for the development. The creation of a central green space in the region of plots 59-72 with houses facing it would give a sense of place, a play area, green space and would result in a less orthogonal plan form giving more interesting rooflines when viewed from outside the site.	now much better provision and location.
5 ii & esign uide		doesn't address the transition into the town - lack of variety in roof heights and orientation – very orthogonal and high density in regimented rows, contrary to the Design Guide. A lot of very similar house types visually.	same comments apply. Sketch on Design statement has some variety in orientation which isn't carried through to the final plan. Roofline very regimented, houses to the east of the access road need a more varied roofline to help the transition from countryside to town.
55 ii			Now mostly retained.
		8m wide maintenance buffer not provided (see design guide –	8m wide maintenance buffer not provided everywhere. (see
		Natural Environment) Social housing not mixed in in contravention of NSDC Affordable	design guide – Natural Environment) Same comment applies
		Housing SPU paras 3.14-3.16 Blank gable ends at the entrance to the site in contravention of Neighbourhood Plan Design Guide	Blank gable ends at the entrance to the site in contravention of Neighbourhood Plan Design Guide. NB Police report refers to this as well, asking for windows in gable ends. They also don't like the rear accesses to several of the social houses.
	O O I I I I I I I I I I I I I I I I I I	15.00% 4b+ 25% 30% 60% of affordable% n/a 5 ix 5 ii & sign ide	beyond which DfT research shows that most people would walk especially if carrying shopping. 225 spaces -two per house generally but 1 per house for 182P houses n/a n/a n/a n/a n/a n/a 30dph 38 dph Doesn't quite conform to DC or NP type %ages although the correct proportion of social housing is very welcome. 65